



We can prevent a costly interruption to your business by predicting equipment failure and production shutdowns.




The IR-Fusion thermal imaging technology from Fluke is the most accurate electrical diagnostic service we offer.

We can detect heat patterns or temperature changes in objects before they turn into costly downtime. We can also monitor developing problems so maintenance can be planned on your schedule and budget.


Predict then prevent problems before they happen

-  Industrial, mechanical, electro-mechanical and general building maintenance.
-  Process, refractory insulation, tank and vessel levels, steam systems and traps, pipes, etc.
-  Electrical, unbalanced loads, overloaded systems, wiring mistakes or component failure, etc.



03/50
Fuse Panel A1
Phase Imbalance

Temperature differences may indicate several issues like harmonics, component problems, bad connections even unbalanced loads



06/50
Cooling Pump Motor F75
No Issues

An overheated motor could indicate electrical power problems, an underrated motor or insufficient cooling.

Don't wait until it's too late.

Call **215-340-4545** now

to see if thermal imaging should be a part of your predictive & preventive maintenance programs.



P.O. Box 1866 Doylestown, PA 18901

E-mail Rich@granahanelectric.com

Fax: 215-340-6262

On the web at www.granahanelectric.com